



























Back view after adding a thin layer of padding.



Front view after all painting, padding
and installation of fabric to exterior.



Rear view showing interesting carpeted foot-rest area for rear passengers.



Front seat unit installed to make sure it fits properly. (Lean-back must be installed first in final installation.)




Final unit, but seat section is not totally pushed back into proper position, but will be later (for ease of handling).




View of front seat unit
from the rear.




Contact cement is applied to the edges and the liner is stretched into place.



Before the headliner installation, ½ inch thick welting had to be installed along the edges of the openings of the doors and unseen fasteners screwed to the edges to hold the edges of the liner.




The sun visors are covered and bound in preparation for installation after the liner has been stretched. Binding the edges is one of the most difficult parts of the job without having the help of the folder and special sewing machine used in the factory.



The sun-visors are installed after the window trim goes in .





The package shelf is covered in carpet ,
installed, and then the divider is put in
place.























